



For operation at low power levels R14 should be changed to a higher value, 100k or even 220k should be tried. This sets the hysteresis level on the current sense

HEI Driver Board (c) 2014 John DeArmond Some Rights Reserved	
TITLE: HEI_Driver	
Document Number:	REV: 1.06
Date: 3/2/14 2:13 PM	Sheet: 1/1

